

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17								
Name of Area - Kunustoria Area, Eastern Coalfields Limited								
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done	
1	Amritnagar Colliery	Amritnagar Colliery	D - Type	1	DEQ/01/002	02.02.2017	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.	
2			C -Type	2	C/02/005	05.12.2016		
3					C/02/006			
4					C/02/007			
5					C/02/008			
6			B - Type	5	B/05/17	19.03.2017		
7					B/05/18			
8					B/05/19			
9					B/05/20			
10			1		B/01/01	04.08.2016		
11					B/01/02			
12					B/01/03			
13					B/01/04			
14			A - Type	2	A/02/005	17.09.2016		
15					A/02/006			
16					A/02/007			
17					A/02/008			
18			3		A/03/009	17.09.2016		
19					A/03/010			
20					A/03/011			
21					A/03/012			
22			13		A/13/49	06.02.2017		
23					A/13/50			
24					A/13/51			
25					A/13/52			
26			NHS	6	NHS/06/47	20.01.2017		
27					NHS/06/48			
28					NHS/06/49			
29					NHS/06/50			
30					NHS/06/51			
31					NHS/06/52			
32					NHS/06/53			
33					NHS/06/54			
34					NHS/06/55			
35					NHS/06/56			
36					2 No Pit Colony			NHS
37			NHS/05/38					
38			NHS/05/39					
39			NHS/05/40					
40			NHS/05/41					
41			NHS/05/42					
42			NHS/05/43					
43			NHS/05/44					
44			NHS/05/45					
45			NHS/05/46					
46			Rly Siding Colony	NHS	10	NHS/10/73		14.05.2016
47						NHS/10/74		
48						NHS/10/75		
49						NHS/10/76		
50						NHS/10/77		
51						NHS/10/78		
52						NHS/10/79		
53						NHS/10/80		
54			NHS	4		NHS/04/25		14.05.2016
55						NHS/04/26		
56						NHS/04/27		
57						NHS/04/28		
58						NHS/04/29		
59						NHS/04/30		

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17								
Name of Area - Kunustoria Area, Eastern Coalfields Limited								
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done	
60			NHS	31	NHS/04/31	21.01.2017	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.	
61					NHS/04/32			
62					NHS/31/241			
63					NHS/31/242			
64					NHS/31/243			
65					NHS/31/244			
66					NHS/31/245			
67		NHS/31/246						
68		1 No Pit	NHS	2	NHS/02/07	25.01.2017		
69					NHS/02/08			
70					NHS/02/09			
71					NHS/02/10			
72					NHS/02/11			
73					NHS/02/12			
74					NHS/02/13			
75					NHS/02/14			
76					NHS/02/15			
77					NHS/02/16			
78		Puranmal	NHS	57	NHS/57/504	29.11.2016		
79					NHS/57/505			
80					NHS/57/506			
81					NHS/57/507			
82					NHS/57/508			
83					NHS/57/509			
84					NHS/57/510			
85					NHS/57/511			
86					NHS/57/512			
87					NHS/57/513			
88					NHS/57/514			
89					NHS/57/515			
90					NHS/57/516			
91					NHS/57/517			
92					NHS/57/518			
93		NHS/57/519						
94			LCH	35	LCH/35/244	06.02.2017		
95					LCH/35/245			
96					LCH/35/246			
97					LCH/35/247			
98					LCH/35/248			
99					LCH/35/249			
100					LCH/35/250			
101					LCH/35/251			
102					LCH/35/252			
103					LCH/35/253			
104		Mahabir Colliery	Durga Mandir	C -Type	C/01/M/02/001	13.02.2017		
105					C/01/M/02/002			
106					C/01/M/02/003			
107					C/01/M/02/004			
108			New Colony	B - Type	2	B -02/005		21.09.2016
109						B -02/006		
110						B -02/007		
111						B -02/008		
112				B - Type	3	B/03/009		28.11.2016
113						B/03/010		
114						B/03/011		
115				B - Type	6	B/03/012		31.10.2016
116		B/06/021						
117		B/06/022						
118					B/06/023			

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17								
Name of Area - Kunustoria Area, Eastern Coalfields Limited								
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done	
119			B - Type	3	B/06/024	19.03.2017	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.	
120					BEQ/03/01			
121					BEQ/03/02			
122			BEQ/03/03					
123			A - Type	13	A - Type	A/13/49		23.07.2016
124						A/13/50		
125						A/13/51		
126						A/13/52		
127			A - Type	14	A - Type	A/14/53		11.08.2016
128						A/14/54		
129						A/14/55		
130						A/14/56		
131			A - Type	15	A - Type	M1/A-15/057		31.10.2016
132						M1/A-15/058		
133						M1/A-15/059		
134						M1/A-15/060		
135			A - Type	16	A - Type	A/16/61		31.03.2017
136						A/16/62		
137						A/16/63		
138						A/16/64		
139			A - Type	17	A - Type	A/17/65		31.03.2017
140						A/17/66		
141						A/17/67		
142						A/17/68		
143			NHS	M/2/01	NHS	NHS/M/2/01/001		12.02.2017
144						NHS/M/2/01/002		
145						NHS/M/2/01/003		
146	NHS/M/2/01/004							
147	NHS/M/2/01/005							
148	NHS/M/2/01/006							
149	NHS/M/2/01/007							
150	NHS/M/2/01/008							
151	NHS	NHS/1/2/	NHS	NHS/1/2/009	06.02.2017			
152				NHS/1/2/010				
153				NHS/1/2/011				
154				NHS/1/2/012				
155				NHS/1/2/013				
156				NHS/1/2/014				
157				NHS/1/2/015				
158				NHS/1/2/016				
159				NHS/1/2/017				
160				NHS/1/2/018				
161				NHS/1/2/019				
162				NHS/1/2/020				
163				NHS/1/2/021				
164				NHS/1/2/022				
165				NHS/1/2/023				
166				NHS/1/2/024				
167	Lal Bungalow	A - Type	A - Type	A/08/M/05/29	14.02.2017			
168				A/08/M/05/30				
169				A/08/M/05/31				
170				A/08/M/05/32				
171	K.S. Unit	A	A	A/25/97	02.05.2016			
172				A/25/98				
173				A/25/99				
174				A/25/100				
175	NHS	11	NHS	NHS/11/113	14.02.2017			
176				NHS/11/114				
177				NHS/11/115				

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17							
Name of Area - Kunustoria Area, Eastern Coalfields Limited							
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done
178					NHS/11/116		Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.
179					NHS/11/117		
180					NHS/11/118		
181					NHS/11/119		
182					NHS/11/120		
183			NHS	5	NHS/05/49	20.02.2017	
184					NHS/05/50		
185					NHS/05/51		
186					NHS/05/52		
187					NHS/05/53		
188					NHS/05/54		
189					NHS/05/55		
190					NHS/05/56		
191			NHS	8	NHS/08/73	19.02.2017	
192					NHS/08/74		
193					NHS/08/75		
194					NHS/08/76		
195					NHS/08/77		
196					NHS/08/78		
197					NHS/08/79		
198					NHS/08/80		
199					NHS/08/81		
200					NHS/08/82		
201					NHS/08/83		
202					NHS/08/84		
203					NHS/08/85		
204					NHS/08/86		
205					NHS/08/87		
206					NHS/08/88		
207		OCP Colony	NHS	M-4-31	M-4-31/311	28.09.2016	
208					M-4-31/312		
209					M-4-31/313		
210					M-4-31/314		
211					M-4-31/315		
212					M-4-31/316		
213					M-4-31/317		
214					M-4-31/318		
215					M-4-31/319		
216					M-4-31/320		
217					M-4-31/321		
218					M-4-31/322		
219			NHS	M/4/24/	NHS/M/4/24/251	30.11.2016	
220					NHS/M/4/24/252		
221					NHS/M/4/24/253		
222					NHS/M/4/24/254		
223					NHS/M/4/24/255		
224					NHS/M/4/24/256		
225					NHS/M/4/24/257		
226					NHS/M/4/24/258		
227		OC Patch	NHS		NHS/M/4/34/347	14.03.2017	
228					NHS/M/4/34/348		
229					NHS/M/4/34/349		
230					NHS/M/4/34/350		
231					NHS/M/4/34/351		
232					NHS/M/4/34/352		
233					NHS/M/4/34/353		
234					NHS/M/4/34/354		
235		More	NHS		NHS/07/065	28.11.2016	
236					NHS/07/066		

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17													
Name of Area - Kunustoria Area, Eastern Coalfields Limited													
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done						
237					NHS/07/067		Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.						
238					NHS/07/068								
239					NHS/07/069								
240					NHS/07/070								
241					NHS/07/071								
242					NHS/07/072								
243		Sahebkhutti	NHS			NHS/20/M/03/215		11.03.2017					
244						NHS/20/M/03/216							
245						NHS/20/M/03/217							
246						NHS/20/M/03/218							
247						NHS/20/M/03/219							
248						NHS/20/M/03/220							
249						NHS/20/M/03/221							
250						NHS/20/M/03/222							
251						NHS						NHS/18/191	22.11.2016
252												NHS/18/192	
253		NHS/18/193											
254		NHS/18/194											
255	NHS/18/195												
256	NHS/18/196												
257	NHS/18/197												
258	NHS/18/198												
259	Parasea Colliery	South Parasea	B - Type	4	B/04/13	15.01.2017							
260					B/04/14								
261					B/04/15								
262					B/04/16								
263			B - Type		6		B/06/21	31.12.2016					
264							B/06/22						
265							B/06/23						
266							B/06/24						
267			B - Type		7		B/07/25	25.01.2017					
268							B/07/26						
269							B/07/27						
270							B/07/28						
271			A - Type		2		A/02/05	23.01.2017					
272							A/02/06						
273							A/02/07						
274							A/02/08						
275			A - Type		4		A/04/13	28.02.2017					
276							A/04/14						
277							A/04/15						
278							A/04/16						
279			A - Type		5		A/05/17	28.12.2016					
280							A/05/18						
281							A/05/19						
282							A/05/20						
283			NHS			1	NHS/01/001	31.01.2016					
284							NHS/01/002						
285							NHS/01/003						
286							NHS/01/004						
287							NHS/01/005						
288							NHS/01/006						
289	NHS/01/007												
290	NHS/01/008												
291	NHS/01/009												
292	NHS/01/010												
293	NHS/01/011												
294	NHS/01/012												
295	NHS/01/013												

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17							
Name of Area - Kunustoria Area, Eastern Coalfields Limited							
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done
296					NHS/01/014		Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.
297					NHS/01/015		
298					NHS/01/016		
299			NHS	4	NHS/04/49	31.01.2017	
300					NHS/04/50		
301					NHS/04/51		
302					NHS/04/52		
303					NHS/04/53		
304					NHS/04/54		
305					NHS/04/55		
306					NHS/04/56		
307					NHS/04/57		
308					NHS/04/58		
309					NHS/04/59		
310					NHS/04/60		
311					NHS/04/61		
312					NHS/04/62		
313					NHS/04/63		
314					NHS/04/64		
315			NHS	5	NHS/05/65	28.01.2017	
316					NHS/05/66		
317					NHS/05/67		
318					NHS/05/68		
319					NHS/05/69		
320					NHS/05/70		
321					NHS/05/71		
322					NHS/05/72		
323					NHS/05/73		
324					NHS/05/74		
325					NHS/05/75		
326					NHS/05/76		
327					NHS/05/77		
328					NHS/05/78		
329					NHS/05/79		
330					NHS/05/80		
331			NHS	6	NHS/06/81	23.02.2016	
332					NHS/06/82		
333					NHS/06/83		
334					NHS/06/84		
335					NHS/06/85		
336					NHS/06/86		
337					NHS/06/87		
338					NHS/06/88		
339					NHS/06/89		
340					NHS/06/90		
341					NHS/06/91		
342					NHS/06/92		
343					NHS/06/93		
344					NHS/06/94		
345					NHS/06/95		
346					NHS/06/96		
347			NHS	16	NHS/16/183	02.09.2016	
348					NHS/16/184		
349					NHS/16/185		
350					NHS/16/186		
351					NHS/16/187		
352					NHS/16/188		
353					NHS/16/189		
354					NHS/16/190		

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17								
Name of Area - Kunustoria Area, Eastern Coalfields Limited								
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done	
355			NHS	17	NHS/17/191	30.12.2016	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.	
356					NHS/17/192			
357					NHS/17/193			
358					NHS/17/194			
359					NHS/17/195			
360					NHS/17/196			
361					NHS/17/197			
362					NHS/17/198			
363					NHS			18
364			NHS/18/200					
365			NHS/18/201					
366			NHS/18/202					
367			NHS/18/203					
368			NHS/18/204					
369			NHS/18/205					
370			NHS/18/206					
371			Central Parasea	NHS	20	NHS/20/21		17.08.2016
372						NHS/20/22		
373		NHS/20/23						
374		NHS/20/24						
375		NHS/20/25						
376		NHS/20/26						
377		NHS/20/27						
378		Dangal Para	NHS	51	NHS/51/482	18.01.2017		
379					NHS/51/483			
380					NHS/51/484			
381					NHS/51/485			
382					NHS/51/486			
383					NHS/51/487			
384					NHS/51/488			
385					NHS/51/489			
386					NHS/51/490			
387					NHS/51/491			
388		OCP Colony	NHS	10	NHS/10/145	10.03.2017		
389					NHS/10/146			
390					NHS/10/147			
391					NHS/10/148			
392					NHS/10/149			
393					NHS/10/150			
394		NHS/10/151						
395		NHS/10/152						
396	Railline Dhowrah	NHS	35	NHS/35/347	17.02.2017			
397				NHS/35/348				
398				NHS/35/349				
399				NHS/35/350				
400				NHS/35/351				
401				NHS/35/352				
402				NHS/35/353				
403				NHS/35/354				
404				NHS/35/355				
405				NHS/35/356				
406	NHS	36	NHS/36/358	15.04.2016				
407			NHS/36/360					
408			NHS/36/361					
409			NHS/36/362					
410			NHS/36/364					
411			NHS/36/365					
412	NHS/36/366							
413	Parasea	NHS	31	NHS/31/312	15.02.2017			

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17													
Name of Area - Kunustoria Area, Eastern Coalfields Limited													
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done						
414			NHS	37	NHS/31/313	15.02.2017	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.						
415					NHS/31/314								
416					NHS/31/315								
417					NHS/ 37/367								
418					NHS/37/368								
419					NHS/37/369								
420					NHS/37/370								
421					NHS/37/371								
422					NHS/37/372								
423					NHS/37/373								
424					NHS/37/374								
425					NHS/37/375								
426					Belbaid Colliery			Belbaid	C - Type	1	C/01/001	15.03.2017	
427											C/01/002		
428											C/01/003		
429	C/01/004												
430	NHS	1				NHS/01/001	09.01.2017						
431						NHS/01/002							
432						NHS/01/003							
433						NHS/01/004							
434						NHS/01/005							
435						NHS/01/006							
436						NHS/01/007							
437						NHS/01/008							
438	NHS	11				NHS/11 /105	17.03.2017						
439						NHS/11 /106							
440						NHS/11 /107							
441						NHS/11 /108							
442						NHS/11 /109							
443						NHS/11 /110							
444	NHS/11 /111												
445						NHS/11 /112							
446	NHS	12				NHS/12/113	17.03.2017						
447						NHS/12/114							
448						NHS/12/115							
449						NHS/12/116							
450						NHS/12/117							
451						NHS/12/118							
452	NHS/12/119												
453						NHS/12/120							
454	NHS	13				NHS/13/121	30.11.2016						
455						NHS/13/122							
456						NHS/13/123							
457						NHS/13/124							
458						NHS/13/125							
459						NHS/13/126							
460						NHS/13/127							
461						NHS/13/128							
462	NHS	14				NHS/14/129	29.11.2016						
463						NHS/14/130							
464						NHS/14/131							
465						NHS/14/132							
466						NHS/14/133							
467						NHS/14/134							
468	NHS/14/135												
469					NHS/14/136								
470	NHS	15			NHS/15/137	14.02.2017							
471					NHS/15/138								
472					NHS/15/139								

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17									
Name of Area - Kunustoria Area, Eastern Coalfields Limited									
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done		
473	Kunustoria Colliery	Kunustoria Colliery	NHS	16	NHS/15/140	15.01.2017	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.		
474					NHS/15/141				
475					NHS/15/142				
476					NHS/15/143				
477					NHS/15/144				
478					NHS/16/153				
479					NHS/16/154				
480					NHS/16/155				
481					NHS/16/156				
482					NHS/16/157				
483					NHS/16/158				
484					NHS/16/159				
485					NHS/16/160				
486					NHS/23/209				
487					NHS/23/210				
488				NHS/23/211					
489				NHS/23/212					
490				NHS/23/213					
491				NHS/23/214					
492				NHS/23/215					
493				NHS/23/216					
494				NHS/26/235					
495				NHS/26/236					
496				NHS/26/237					
497				NHS/26/238					
498				NHS/26/239					
499				NHS/26/240					
500				NHS/26/241					
501				NHS/26/242					
502				NHS/26/243					
503				NHS/26/244					
504				NHS/30/001					
505				NHS/30/002					
506				NHS/30/003					
507				NHS/30/004					
508				NHS/30/005					
509				NHS/30/006					
510				NHS/30/007					
511				NHS/30/008					
512				NHS/30/009					
513				NHS/30/010					
514				C - Type				CEQ/GF/04	31.08.2016
515								CEQ/GF/05	31.05.2016
516								CEQ/GF/07	
517				B - Type				BEQ/GF/01	19.08.2016
518								BEQ/GF/02	
519								BEQ/GF/03	
520								BEQ/GF/04	
521								BEQ/GF/05	
522								BEQ/GF/06	
523				A - Type				A/GF/17	26.08.2016
524								A/GF/18	
525								A/GF/19	
526				A/GF/20					
527	NHS		16	NHS/ACC/16/143	30.09.2016				
528				NHS/ACC/16/144					
529				NHS/ACC/16/145					
530				NHS/ACC/16/146					
531				NHS/ACC/16/147					

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17													
Name of Area - Kunustoria Area, Eastern Coalfields Limited													
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done						
532					NHS/ACC/16/148		Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.						
533					NHS/ACC/16/149								
534					NHS/ACC/16/150								
535					NHS/ACC/16/151								
536					NHS/ACC/16/152								
537					NHS			17	NHS/ACC/17/153	15.04.2016			
538									NHS/ACC/17/154				
539									NHS/ACC/17/155				
540									NHS/ACC/17/156				
541									NHS/ACC/17/157				
542									NHS/ACC/17/158				
543									NHS/ACC/17/159				
544									NHS/ACC/17/160				
545									NHS/ACC/17/161				
546									NHS/ACC/17/162				
547									NHS		8	NHS/ACC/08/67	09.11.2016
548												NHS/ACC/08/68	
549					NHS/ACC/08/69								
550					NHS/ACC/08/70								
551					NHS/ACC/08/71								
552					NHS/ACC/08/72								
553					NHS/ACC/08/73								
554					NHS/ACC/08/74								
555					NHS/ACC/08/75								
556					NHS/ACC/08/76								
557					NHS			4	NHS/ACC/04/27	09.11.2016			
558									NHS/ACC/04/28				
559									NHS/ACC/04/29				
560									NHS/ACC/04/30				
561									NHS/ACC/04/31				
562									NHS/ACC/04/32				
563									NHS/ACC/04/33				
564									NHS/ACC/04/34				
565									NHS/ACC/04/35				
566									NHS/ACC/04/36				
567					NHS			20	NHS/ACC/20/183	29.11.2016			
568									NHS/ACC/20/184				
569									NHS/ACC/20/185				
570									NHS/ACC/20/186				
571									NHS/ACC/20/187				
572									NHS/ACC/20/188				
573									NHS/ACC/20/189				
574									NHS/ACC/20/190				
575									NHS/ACC/20/191				
576									NHS/ACC/20/192				
577									NHS		55	NHS/ACC/55/07	29.11.2016
578												NHS/ACC/55/08	
579					NHS/ACC/55/09								
580					NHS/ACC/55/10								
581					NHS/ACC/55/11								
582					NHS/ACC/55/12								
583					NHS/ACC/55/13								
584					NHS/ACC/55/14								
585					NHS/ACC/55/15								
586					NHS/ACC/55/16								
587					Bansra Colliery			Bansra	C - Type	1	C/01/001	04.03.2017	
588	C/01/002												
589	C/01/003												
590	C/01/004												

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17							
Name of Area - Kunustoria Area, Eastern Coalfields Limited							
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done
591			A - Type	5	A/05/005	28.01.2017	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.
592					A/05/006		
593					A/05/007		
594					A/05/008		
595			NHS	1	NHS/01/001	28.02.2017	
596					NHS/01/002		
597					NHS/01/003		
598					NHS/01/004		
599			NHS	4	NHS/04/29	10.02.2017	
600					NHS/04/30		
601					NHS/04/31		
602					NHS/04/32		
603					NHS/04/33		
604					NHS/04/34		
605					NHS/04/35		
606					NHS/04/36		
607					NHS/04/37		
608					NHS/04/38		
609			NHS	23	NHS/23/201	23.02.2017	
610					NHS/23/202		
611					NHS/23/203		
612					NHS/23/204		
613					NHS/23/205		
614					NHS/23/206		
615					NHS/23/207		
616					NHS/23/208		
617					NHS/23/209		
618					NHS/23/210		
619					NHS/23/211		
620					NHS/23/212		
621					NHS/23/213		
622					NHS/23/214		
623					NHS/23/215		
624					NHS/23/216		
625			NHS	24	NHS/24/217	25.02.2017	
626					NHS/24/218		
627					NHS/24/219		
628					NHS/24/220		
629					NHS/24/221		
630					NHS/24/222		
631					NHS/24/223		
632					NHS/24/224		
633					NHS/24/225		
634					NHS/24/226		
635					NHS/24/227		
636					NHS/24/228		
637			NHS/24/229				
638			NHS/24/230				
639			NHS/24/231				
640			NHS/24/232				
641			NHS	28	NHS/28/273	16.01.2017	
642					NHS/28/274		
643					NHS/28/275		
644					NHS/28/276		
645					NHS/28/277		
646					NHS/28/278		
647					NHS/28/279		
648					NHS/28/280		
649			LCH	8	LCH/08/69	08.02.2017	

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17														
Name of Area - Kunustoria Area, Eastern Coalfields Limited														
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done							
650					LCH/08/70		Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.							
651					LCH/08/71									
652					LCH/08/72									
653					LCH/08/73									
654					LCH/08/74									
655					LCH/08/75									
656					LCH/08/76									
657					LCH/08/77									
658					LCH/08/78									
659									LCH	7	LCH/07/59	22.02.2017		
660											LCH/07/60			
661											LCH/07/61			
662											LCH/07/62			
663					LCH/07/63									
664	North Searsole Colliery	NSC	B - Type	7	B/07/23	09.04.2016								
665					B/07/24									
666					B/07/25									
667					B/07/26									
668	AHQ	Area Residential Comp	D - Type		D/01	31.12.2016								
669					D/02									
670					D/03									
671					D/04									
672					D/05									
673					D/06									
674					D/07									
675					D/08									
676							DEQ -1	28.02.2017						
677							DEQ - 2	23.03.2017						
678					C - Type		C/009	15.02.2017						
679											C/010			
680											C/011			
681											C/012			
682					B - Type		B/13	07.01.2017						
683											B/14			
684											B/15			
685											B/16			
686											B/25			
687											B/26			
688											B/27			
689											B/28			
690									B/45	28.02.2017				
691									B/46					
692									B/47					
693									B/48					
694							B/17	06.01.2017						
695							B/18							
696							B/19							
697							B/20							
698							B/49							
699							B/50							
700					B/51									
701					B/52									
702			A - Type		A/09	28.02.2017								
703									A/10					
704									A/11					
705									A/12					
706									A/13					
707									A/14					
708									A/15					

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17											
Name of Area - Kunustoria Area, Eastern Coalfields Limited											
Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done				
709		Area Hospital Complex	C - Type		A/16	31.01.2017	Thorough internal and external repairing done alongwith repairing of sanitary installations, drainage system, water supply, doors & windows, electrical.				
710					C/05						
711					C/06						
712					C/07						
713					C/08						
714					C/09						
715					C/10						
716					C/11						
717					C/12						
718					B - Type					B/09	25.01.2017
719										B/10	
720										B/11	
721		B/12									
722		B/21									
723		B/22									
724		B/23									
725		B/24									
726		A - Type			A/01	15.07.2016					
727					A/02						
728					A/03						
729					A/04						
730		Store backside	NHS		NHS/17	19.01.2017					
731					NHS/18						
732					NHS/19						
733					NHS/20						
734					NHS/21						
735					NHS/22						
736					NHS/23						
737					NHS/24						
738		MT Hostel Complex	NHS		NHS/012	15.02.2017					
739					NHS/013						
740					NHS/014						
741	NHS/015										
742	NHS/016										
743	NHS/017										
744	NHS/018										
745	NHS/019										
746	NHS/020										
747	NHS/021										
748	NHS/022										
749	NHS/023										
750	NHS/024										
751	NHS/025										
752	NHS/026										
Total nos. of quarters repaired - 752 nos.											