

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17

Name of Area - S.P. Mines Area, Eastern Coalfields Limited

Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done						
1	Chitra	Old Colony	NHS	1	1	21.01.2017	Thorough internal and external repairing alongwith repairing of sanitary installations, water supply, doors window, elctrical wiring. Providing fixing floor and wall tiles in kitchen toilet and bathroom. Providing and fixing wash basin, mirror and exhaust fan in kitchen.						
2					2								
3					3								
4					4								
5					5								
6					6								
7					7								
8					8								
9					9								
10					12								
11					13								
12					14								
13					15								
14					16								
15									NHS	3	34	13.03.2017	
16					36								
17			37										
18			38										
19			39										
20			40										
21			42										
22			43										
23			44										
24			45										
25			46										
26			48										
27					NHS	4		49	25.01.2017				
28			50										
29			52										
30			54										
31			55										
32			56										
33			57										
34			58										
35			59										
36			60										
37			61										
38			62										
39			63										
40			64										
41					NHS	6		81		13.03.2017			
42			82										
43			83										
44			84										
45			85										
46			87										
47			88										
48			89										
49			90										
50			91										
51			92										
52			93										

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17

Name of Area - S.P. Mines Area, Eastern Coalfields Limited

Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done
53					94		Thorough internal and external repairing alongwith repairing of sanitary installations, water supply, doors window, elctrical wiring. Providing fixing floor and wall tiles in kitchen toilet and bathroom. Providing and fixing wash basin, mirror and exhaust fan in kitchen.
54					95		
55			NHS	8	113	09.01.2017	
56					114		
57					115		
58					116		
59					117		
60					118		
61					119		
62					120		
63					121		
64					122		
65					123		
66					124		
67					125		
68					126		
69					128		
70			NHS	9	129	23.01.2017	
71					130		
72					131		
73					132		
74					133		
75					134		
76					136		
77					137		
78					138		
79					139		
80					140		
81					143		
82					144		
83			NHS	10	145	25.01.2017	
84					146		
85					147		
86					148		
87					149		
88					150		
89					151		
90					152		
91					157		
92					158		
93					159		
94			NHS	11	161		21.01.2017
95					162		
96					164		
97					165		
98					167		
99					168		
100					172		
101					174		
102					175		
103					176		
104			B - Type	1	1	25.01.2017	

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17

Name of Area - S.P. Mines Area, Eastern Coalfields Limited

Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done
105					2		Thorough internal and external repairing alongwith repairing of sanitary installations, water supply, doors window, elctrical wiring. Providing fixing floor and wall tiles in kitchen toilet and bathroom. Providing and fixing wash basin, mirror and exhaust fan in kitchen.
106			B - Type	3	3	19.02.2017	
107					4		
108			B - Type	6	11	26.01.2017	
109					12		
110			B - Type	17	50	12.01.2017	
111					51		
112					52		
113			B - Type	18	53	25.01.2017	
114					54		
115					56		
116			B - Type	19	57	14.03.2017	
117					58		
118					59		
119					60		
120			B - Type	20	61	22.02.2017	
121					62		
122					63		
123					64		
124			D - Type	1	1	26.01.2017	
125				2	1		
126				3	1		
127				4	1		
128		New Colony	NHS	14	209	14.02.2017	
129					210		
130					211		
131					212		
132					214		
133					215		
134					216		
135					218		
136					221		
137					224		
138			NHS	16	241	25.01.2017	
139					242		
140					243		
141					244		
142					245		
143					246		
144					247		
145					248		
146					249		
147					250		
148					251		
149					252		
150					253		
151					254		
152					255		
153					256		
154			NHS	20	297	22.01.2017	
155					298		
156					299		

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17

Name of Area - S.P. Mines Area, Eastern Coalfields Limited

Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done
157					300		Thorough internal and external repairing alongwith repairing of sanitary installations, water supply, doors window, elctrical wiring. Providing fixing floor and wall tiles in kitchen toilet and bathroom. Providing and fixing wash basin, mirror and exhaust fan in kitchen.
158					301		
159					302		
160					303		
161					305		
162					306		
163					307		
164					308		
165					309		
166					310		
167					311		
168					312		
169			NHS	21	313	22.01.2017	
170					314		
171					315		
172					316		
173					317		
174					318		
175					319		
176					320		
177					321		
178					322		
179					323		
180					324		
181					325		
182					326		
183					327		
184					328		
185			NHS	23	346	25.12.2016	
186					347		
187					348		
188					349		
189					350		
190					351		
191					352		
192					354		
193					355		
194					356		
195					357		
196					358		
197					359		
198					360		
199			NHS	34	465	28.01.2017	
200					466		
201					467		
202					468		
203					469		
204					470		
205					471		
206					472		
207					474		
208					475		

Details of Individual Quarters Repaired under Block Repairing Programme during the Year 2016-17

Name of Area - S.P. Mines Area, Eastern Coalfields Limited

Sl. no.	Name of Colliery	Name of Colony	Type of Quarter	Block No.	Quarter no.	Date of completion	Type of Repairing Done
209					476		Thorough internal and external repairing alongwith repairing of sanitary installations, water supply, doors window, elctrical wiring. Providing fixing floor and wall tiles in kitchen toilet and bathroom. Providing and fixing wash basin, mirror and exhaust fan in kitchen.
210					477		
211					478		
212					479		
213					480		
214			NHS	37	513	19.02.2017	
215					514		
216					515		
217					516		
218					517		
219					518		
220					519		
221					520		
222			NHS	30	433	19.02.2017	
223					434		
224					435		
225					436		
226					437		
227					438		
228					439		
229					440		
230			NHS	31	441	19.02.2017	
231					442		
232					443		
233					444		
234					445		
235					446		
236					447		
237					448		
238			B - Type	9	18	22.02.2017	
239					19		
240					20		
241			B - Type	11	26	26.01.2017	
242					27		
243					28		
244			B - Type	13	33	24.01.2017	
245					34		
246					35		
247					36		
248			B - Type	14	37	25.01.2017	
249					38		
250					39		
251					40		
Total nos. of quarters repaired - 251 nos.							